

Parts Numbers for SSB-2010/1001B

1. Not Replaceable

2. 244039-000
(\$0.85)

3. 912020-000
(\$225.00)

4. 283003-000
(\$1.00)

5. 242001-000 & 213006-000
(\$5.00) (\$7.00)

6. 900270-000
(\$69.00)

7. 911064-7
(\$1,125.00)

8. H018-1
(\$5.00)

8a 244039-000
(\$0.50)

9. P228-3
(\$6.00)

10. 914016-000
(\$10.00)

11. 283002-000
(\$1.00)

12. H024
(\$6.00)

13. H018
(\$5.00)

13a 244031-00
(\$0.50)

14. 911024-000
(\$40.00)

15. 245004-000
(\$0.50)

16. 244015-000
(\$0.50)

17. 244020-000
(\$0.50)

17a 161022-000
(\$3.75)

